

Fig. 1A




Fig. 1B




Fig. 1C




Fig. 2A




Fig. 2B




Fig. 2C




Fig. 2D




Fig. 3A




Fig. 3B




Fig. 3C

2/8




Fig. 4A




Fig. 4B




Fig. 4C




Fig. 4D

FOOT 429500T




Fig. 5A




Fig. 5B




Fig. 5C




Fig. 5D




Fig. 5E




Fig. 5F




Fig. 5G




Fig. 5H




Fig. 5I




Fig. 5J




Fig. 5K




Fig. 5M




Fig. 5L




Fig. 5N




Fig. 5O




Fig. 5P




Fig. 5Q




Fig. 5R

10016174 103001

5/8




Fig. 5S




Fig. 5T




Fig. 5U




Fig. 5V




Fig. 5W







Fig. 5X

10016174-103001

6/8






Fig. 7





Fig. 8A






Fig. 8C

10036374-103001